

Measuring devices

7KT1 3 Multimeters

Schematics

Instructions for the connection of transformer counters

In the case of cross-section reduction, a short-circuit resistant cable is required for the power supply of terminal 2, depending on the fusing for phases L1, L2, L3. A fuse of 6 A is recommended for the line protection.

Current transformers must not be operated with open terminals as dangerously high voltages can occur, which may result in personal injuries and property damage. It may also lead to a thermal overload of the transformers.

