

Selection and Ordering data		Order No.
SITRANS TF280 WirelessHART Temperature transmitter (Required battery not included with delivery, see accessories)	▶	7MP 1 1 1 0 - 0 A - 0 0
Connections/cable entry Cable gland M20x1.5 ¹⁾ Sensor pipe with Pt100, G½" male thread, pre-mounted and connected		C D
Display Digital display, visible		1
Enclosure Die-cast aluminum		1
Explosion protection Not included		A
Antenna Variable, attached to device		A
Further designs Please add "-Z" to Order No. and specify Order code(s) and plain text.		Order code
Measuring point number (TAG Nr.) max. 16 digits entered in plain text Y15:		Y15
Measuring point message max. 27 characters entered in plain text: Y16:		Y16
Accessories		Order No.
Lithium battery for SITRANS TF280/P280	▶	7MP1990-0AA00
Mounting bracket, steel		7MF4997-1AC
Mounting bracket, stainless steel	▶	7MF4997-1AJ
Cover, die-cast aluminum, without window	▶	7MF4997-1BB
Cover, die-cast aluminum, with window		7MF4997-1BE
Thread adapter M20x1.5 (male thread) on ½-14 NP (female thread)	▶	7MP1990-0BA00
Thread adapter M20x1.5 (male thread) on G½B (female thread)	▶	7MP1990-0BB00
IE/WSN-PA Link		see Chap. 8
HART modem with RS232 interface	▶	7MF4997-1DA
HART modem with USB interface	▶	7MF4997-1DB
SIMATIC PDM		see Chap. 8

1) Please order sensor separately.