Selection and Ordering data		Order No.	Selection and Ordering data	Orc	der No.
MFA 4P Motion Failure Alarm Controller	C)	7MH7144 -			IH 7 1 4 6 -
A highly sensitive single setpoint motion sens system, used with MSP and XPP probes.	1		A series of motion sensing probes used with the MFA 4p.	0	
Enclosure NEMA 4X, polycarbonate enclosure NEMA 4, painted mild steel enclosure NEMA 4X, stainless steel enclosure		1 2 3	Milltronics MSP-1: miniature motion sensing probe Milltronics MSP-3: heavy-duty, high temperature aluminum Milltronics MSP-9: heavy-duty, high temperature stainless steel		
Input Voltage 100/115/200/230 V AC, 50/60 Hz, switch sele	ctable	A	Milltronics MSP-12: heavy-duty, general purpose Milltronics XPP-5: hazardous rate  Note: Milltronics MSP-1, MSP-3 and MSP-9 probes		
Speed detection version Standard, underspeed (U/S) or overspeed (C	)/S),	A	require the use of Milltronics RMA (amplifier)  Model	_	
switch selectable Slow speed (S/S), U/S or O/S detection, switch selectable	ch	В	MSP-1 with 1.8 m (6 ft) of cable MSP-3, 1/2" NPT cable inlet with 1.5 m (5 ft) high temperature cable	A B	
Approvals CE, CSAus/c, FM		2	MSP-9 with 1.5 m (5 ft) high temperature cable	D	·
		2	MSP-12, 1/2" NPT cable inlet	E	
Instruction manual English French	′	7ML1998-5FM01 7ML1998-5FM11	XPP-5, with 1.5 m (5 ft) cable, (CSA Class I, Group A, B, C and D; Class II Group E, F and G) XPP-5, with 10 m (32.8 ft) cable, (CSA Class I,	G H	
Spanish		7ML1998-5FM21	Group A, B, C and D; Class II Group E, F and G)		
German  Note: The instruction manual should be order a separate item on the order.		7ML1998-5FM31	XPP-5, with 15 m (49.2 ft) cable, (CSA Class I, Group A, B, C and D; Class II Group E, F and G)	J	
This device is shipped with the Siemens Millt manual CD containing the complete instruction manual library.			Approvals CE		A
Spare parts Relay Transformer Circuit Card, standard Circuit Card, Slow speed	,	7MH7723-1DW 7MH7723-1DX 7MH7723-1DU 7MH7723-1DV	French Spanish	C) 7M C) 7M	IL1998-5FM01 IL1998-5FM11 IL1998-5FM21 IL1998-5FM31
C) Subject to export regulations AL: N, ECCN: E	AR99		Spare parts	_	
			Locknut, for MSP-1	7M	IH7723-1CQ
Selection and Ordering data		Order No.			IH7723-1CR
Milltronics RMA Remote Mounted Amplifie	er C)	7MH7145-	Mounting flange, for MSP-3, MSP-4, MSP-12, XPP-5	/ IVI	IH7723-1CS
Remote mounted amplifier for Milltronics MSF MSP-3 and MSP-9 motion sensing probes.	P-1,	0	Mounting bracket for MSP-9 Lid, 1/2" NPT cable inlet, for MSP-3, MSP-12		IH7723-1CT IH7723-1CU
Enclosure Aluminum enclosure, 1/2" NPT entry		A	Lid for MSP-9	7M	IH7723-1CV
Painted steel, NEMA 4 rating Stainless steel enclosure, NEMA 4X rating		C	Lid gasket, for MSP-3, MSP-9 Lid gasket, for MSP-12		IH7723-1CW IH7723-1CX
Instruction manual			C) Subject to export regulations AL: N, ECCN: EAR99		
English		7ML1998-5FM01			
French		7ML1998-5FM11 7ML1998-5FM21			
Spanish German Note: The instruction manual should be order	C)	7ML1998-5FM31			
a separate item on the order.					
Spare parts Card, RMA	C)	7MH7723-1DT			

C) Subject to export regulations AL: N, ECCN: EAR99